



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 12/08/2014

Reviewed

PPB

Mine Name: Black Butte	Permit Number: S/015/0080	Mine Status: Active
Operator Name: Goldterra Inc.	Inspection Date: 12/08/2014	Permit Fees: Paid
Inspector(s): Wayne Western	Inspection Time: 12:01 - 12:40 pm	Bond Amount: \$7,600
Attendee(s):	Weather: mild and clear	Bond Escalation: 03/26/2014
Inspection Purpose: Routine inspection		Prior Inspection: 10/30/2014

Conclusions and Recommendations

The purpose of the inspection was to monitor the contractor at the site. The contractor was reclaiming the road and cleaning up the site. The site had been previously disturbed by with pits. The pits had been backfilled prior to current reclamation work. There were rebar stake on site for a grid which were removed. Reclamation most consisted of pocking the road from the site to the check dam which is outside of the permit boundary.

Elements of Inspection	Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds The Operator is in the process of reclaiming the site for bond release.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls) The area is most flat with no underground openings or highwalls. No trash or signs were on site.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages/Erosion Control Erosion controls for the reclaimed site consist of pocking. The site is flat and there were no signs of erosion within the permit boundary.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material None present. All rebar had been removed.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety) The main reclamation activity was to pock the road from the reclaimed pits to the check dam. The pocks were approximately 18 inch long, 18 inches wide and 6 inches deep.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation Contractor will seed the area.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature:

Wayne Western

CC:

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M015-Emery/S0150080-BlackButte/inspections/Insp12082014.pdf





Looking west. Contractor is pocking the access road.



Rebar had been removed from the site.



Looking west. Operator is pocking the access road. Note the mine area has been reclaimed some years ago.



White truck in the left show were the pocking will stop. The road will to the check dam will be left in place.